

Storage Instruction to avoid possible problems following poor packaging

In order to gain on pallet dimension and save transport cost, CTL tracks or Mini-X tracks are sometimes shipped to the customer as below.



If the tracks stay palletised like this during a long time, at the moment of the fitting on the machine it will create vibration issue due to wave shape. This problem will be accentuated if the weather is cold.

SHORT-TERM SOLUTION:

Inform the customer to check in their stock if they have no tracks badly conditioned

LONG-TERM SOLUTION:

On the next page, an information you can cut, plastify and attach to the product if you send to your customer a track palletized reverse bended.

COMMUNICATION

A complete document will be send soon in order to inform you about the suitable instruction in the storage area.

Please direct any questions or concerns to the Product Support team. Your feedback, observation or criticism are welcome in order to steadily improve our products.



PRODUCT SUPPORT TEAM

WORLDWIDE

David De Waele

Product Line Director Tracks EMEA, Technical support & Warranties

Camoplast Solideal

Ghent, Belgium

Tel: +32 (0)9 259 10 33

david.dewaele@camoplastsolideal.com

EUROPE

Chrystel Bouvard

Technical Support, Tracks and Warranties, EMEA – Construction

Camoplast Solideal

Malesherbes, France

Tel.: +33 (0)2.38.32.72.19

chrystel.bouvard@camoplastsolideal.com

AMERICAS

Paul Vanasse

Technical Support, Tracks and Warranties, Americas – Construction

Camoplast Solideal

Magog, Canada

Tel.: 819-868-1500, ext. 3516

paul.vanasse@camoplastsolideal.com



camoplast

HI-PERFORMANCE TRACKS

Dear Customer,
In order to avoid problem at the moment of adaptation of the track on the machine, please store your track according to the below condition.



STORAGE
RECOMMENDATION


camoplast
HI-PERFORMANCE TRACKS